



No.: 0001

Equipment Plus Parts Pty Ltd
Phone: 1300 004 EWP (1300 004 397)
Email: service@eplusp.com.au
Web: www.equipmentplusparts.com.au
Address: A1 Salmon Close Cranebrook 2749

Scissor Lift Checklist

Customer Name: Equip Hire Make JLG Model ES1932

Plant/Asset No: _____ Serial Number: G200005459 Machine Hours: 53.1 DOM: 2022

☐ Off hire Inspection ☐ 90 Day Inspection ☐ Annual Inspection

Check Points	OK	N/A	Fail	Comments
Ground Controls: Has correct key and controls function correctly.	✓			
Emergency lowering: Cable is free. Valve works correctly. Electric motor and pump operate correctly.	✓			
Document Box: Present and has operator's manual fitted.	✓			
Emergency Stops: All are functioning correctly.	✓			
Safety Decals: None missing, are legible and free of damage.	✓			
Lights: Strobe, work, and warning lights all operational.	✓			
Electric Machine: Battery Check: water levels, cables, and terminals for cleanliness. Correct type fitted to machine. Charger functioning. Electric motors are clean and cable tight. Clamp present.	✓			
Diesel Machine: Engine check - Fluid levels, glow plugs, RPM, fanbelt, air cleaner and any leakages. Exhaust tight and free of damage.		✓		
Stabilizer Legs: Operate correctly. Feet are present and tight		✓		
Hydraulic system: Oil level OK, no leaks, and hose condition. Cylinders - no visible damage or leaks both internally or externally.	✓			
Scissor Stack: Arms free of damage, no cracked welds (visual). Pins and bushes tight with retaining hardware not missing. Slides not worn out. Wiring and hoses free of damage. Safety prop present. Limit switches present and operating correctly.	✓			
Pot hole protection: System deploys and retracts correctly.	✓			
Platform: Handrails free of damage and not missing retaining clips. Gate self closes and locks. Deck extension slides freely and locks into place. Floor free of damage.	✓			
Platform controls: Dead man operates correctly. Check drive speeds are correct for stowed & elevated. Joystick returns to neutral when released. Control box wiring free of damage. Crush protection operates correctly.	✓			
Brakes: Operate correctly.	✓			
Wheel Bearings: No excessive movement.	✓			
Alarms: Horn operates. Motion alarm operates. Tilt sensor/alarm operates and cuts out machine.	✓			
Test and tag: In date on charger and power to platform. RCD OK.	✓			
Fire Extinguisher: Charged, clean and in date. Tag stamped.		✓		
Wheels: No gouges/excessive wear. Wheel nuts correct tension.	✓			
Overall appearance: Paint, cleanliness, static strap fitted. Lift is free of unauthorised modifications. Doors/covers all close/lock.	✓			
Grease and lubricate: Machine as per service manual.	✓			
Reduction Hubs: Free from leaks, oil levels ok and no debris tangled around them.	✓			
Annual service (if required): Oils & filters changed as required. Change grey card. Plate stamped (if applicable).	✓			
Final Check: Fit service sticker. Fill in log book. Fit test and tag sticker. Check work area is clean.	✓			

The undersigned certifies that the machine has been inspected and any discrepancies have been brought to the attention of the owner/user and that all discrepancies have been corrected prior to any further use of this machine.

Inspected by (Name):

F YOUNG

Inspected by (Signature):

Date:

01-04-2025